

Sharp Shoot-R Precision Products



Instructions for using WIPE-OUT

Revolutionary New Product because its BRUSHLESS.....NOW IMPROVED - 25% stronger

PUT IN A GUN YOU THINK IS CLEAN.....!!!! WIPE-OUT™, a revolutionary product that solves all problems encountered with conventional bore cleaners. Traditional products may have a pleasant smell, but are totally in-effective for cleaning a firearm. Loss of accuracy is normal in all firearms after they have been used in a prolonged shooting session. The barrel will become fouled with gunpowder residue as a result of combustion, additionally: two other materials are deposited internally to the barrel,..... carbon and metal fouling from bullet material . These two are the most difficult to remove and are the greatest cause for the loss of accuracy in a firearm. The standard practice has been to dunk a brush into the cleaner and stroke the cleaning rod the length of the bore. By the way use a bore guide and a coated cleaning rod, this is a good way to prevent damage the bore, crown, and the throat. A good deal of the evidence of fouling removal comes from the bristles in the brush itself, (copper or bronze.)A more recent approach has been to product products with heavy amounts of acid and ammonia. While acid and ammonia will remove metal fouling and carbon they are dangerous to you and your firearm. Products containing large amounts of acids and ammonia still require large amounts of brushing.The major problem also is a horrible smell, and they are very dangerous to the steel used in gun barrels. There are many sad shooters who have pitted a barrel using cleaners of this type. It is quite easy using these products to permanently damage the interior of the barrel with pitting. But Not With WIPE-OUT !

Count the number of strokes you take using conventional acid and ammonia base cleaners. Conservatively it is over **100 strokes**. Take that number times the number of times you clean your firearm (monthly or annually or weekly), and then again multiply the number of years you have owned the piece. Conservatively you will have a number in the thousands of strokes you put thru that barrel. It is impossible to put a cleaning rod into the best of barrels several hundred thousand strokes without compromising the quality of the barrel in some way. **With WIPE-OUT™ each cleaning session takes no more than 2 or 3 patches.** **BOTTOM LINE IS THAT WIPE-OUT™ WILL KEEP A GREAT BARREL IN PREMIUM CONDITION LONGER THAN ANY OTHER CLEANING METHOD. BRUSHING A BARREL IS "DARK AGES" TECHNOLOGY.**

INSTRUCTIONS FOR USE OF-----WIPE-OUT™ THE FIRST FIREARM YOU CLEAN WITH WIPE-OUT™ SHOULD BE ONE YOU THINK IS CLEAN. .

Simply hold the applicator tip against the muzzle or bore guide and apply the WIPE-OUT™. All that is necessary is a short burst, generally a -two count works. WIPE-OUT™ designed to rapidly expand into the barrel, like shaving cream. The applicator tip may also be reversed for large caliber firearms or muzzle loading firearms up to 62 caliber. WIPE-OUT™ may be applied to the breech end by removing the adapter on the nozzle and replacing it with a plastic soda straw(Mc Donald's or Subway has the right size). Push the straw into the neck of the chamber and apply. We introduced a great new applicator that has an 8" hose the WSA-007.

WIPE-OUT™ tells you when your firearm is fouled with powder residue, carbon, and metal fouling by the color left on a patch. What you must do is get to a clean barrel, where you have no color showing on a patch. Simply apply WIPE-OUT™ to the muzzle or to the chamber(with the use of a bore guide)or the plastic soda straw on the can spout until the barrel is full.

Set the firearm on the bench horizontally. Let it sit for 60 minutes. Heavily fouled guns or those cleaned with other products should be left overnight on the first cleaning. Patch out in the morning. Re-apply WIPE-OUT™ and wait 10 minutes. Patch out and check for any color. If color is present.....re-apply and let set overnight. Repeat the morning procedure. Once the gun is really clean,a normal shooting session (20 to 60 rounds) can be cleaned in less than one hour. **You have to get the barrel clean to start with.....The reason we ask you to start with a gun you think is cleanis so that you will understand what ineffective cleaners have been leaving in your barrel. Also there may be a distinct layering effect of fouling which is caused by ineffective cleaning. The barrel may actually have as many as 7 or 8 layers of fouling which is probably the most difficult to remove. The barrel with this type of fouling may take 3 or 4 overnight applications of Wipe-Out™ to finally get to a clean patch with no color.** After 20 minutes has elapsed, push a clean cotton patch on a jag through the bore .

Powder fouling (both smokeless powder and black powder) will be grayish black on the patch .Copper fouling will be deep navy blue.Carbon will be tannish to brown in color . Please be aware that large amounts of fouling on a very dirty firearm can build up in layers.

IF THERE IS NO COLOR ON THE PATCH.....THE FIREARM IS CLEAN.

IF THERE IS **ANY** COLOR ON THE PATCH: Apply the WIPE-OUT™ again to the barrel.

If the first patch showed all three colors, the gun is heavily fouled. Let the gun set for 60 minutes or more . You are assured that as long as its in the jell state, WIPE-OUT™, is still working . Push a clean patch through the bore. If there is still color on the patch re-apply and set for a longer period of time. Whenever possible the easiest method using WIPE-OUT™ is to LET IT SET OVERNIGHT.

REMEMBER THE FOLLOWING:A PATCH WITH NO EVIDENCE OF COLOR IS EVIDENCE OF A CLEAN FIREARM . Deep navy blue on a patch is evidence of heavy copper fouling .In cases where the firearm has not been properly cleaned, or shot quite a number of times (varmint shooting) WIPE-OUT™ may be applied and the gun left to set overnight, with no harm to the firearm. Patch out the bore in the morning , Re-apply WIPE-OUT™ , and let firearm set 60 minutes. There should be NO EVIDENCE OF COLOR ON A PATCH. Always let the firearm rest horizontally.....never muzzle-up when using WIPE-OUT™.

Removal of metal fouling and carbon along with powder fouling will restore accuracy to unclean firearms . We have found many firearms that were thought to be "shot-out", when cleaned properly, the original accuracy was restored . These guns were simply cleaned ineffectively. WIPE-OUT™ cleans the bore without brushing .

WIPE-OUT™ RESTORES BARREL LIFE AND ACCURACY TO THESE GUNS.WIPE-OUT™ is odorless and non-flammable, It contains a rust inhibitor, and will not stain hands of clothing .While safe for all modern paint, gunstock finishes and steels.

WIPE-OUT™ is not safe for varnish , shellac, laquer, TRU-OIL, LIN-SPEED, linseed oil or tung oil, or old oil type finishes. It will remove them. However WIPE-OUT™ is safe for all modern finishes - poly urethanes and epoxies. It will dissolve brass, bronze, and copper. Most aluminum (AR-15/M-16 receivers and all aluminum pistol frames) are safe with Wipe-Out™ , but some will discolor to a dull grey. IF you have any doubt try a test area where it will not be visible. Wipe-Out™ will NOT DISSOLVE LEAD but it will degrade lead so that it can be pushed out with a patch.WIPE-OUT™ contains no acid and no ammonia.WIPE-OUT™ CANNOT CAUSE RUST.It will not gum, or form solids in either the action or the barrel .WIPE-OUT™ is safe for all barrel steels, both stainless and carbon steel. NOTE: WIPE-OUT will remove Molybdenum. SAFETY and PRECAUTIONS WIPE-OUT is low in ph and because it is odorless it appears to be quite safe. However prolonged contact may cause damage to the eyes and skin. Be careful to clean hands and skin after using the product.Flush, immediately if the product gets into the eyes. Keep out of the reach of children . Always follow good safety procedures with this product. Do not ingest Keep out of the reach of children. Do not incinerate the can.Do not store in temperatures above110 degrees Fahrenheit . WIPE-OUT™ is a convenient to use and will completely clean a BLACK POWDER FIREARM in a few minutes. There is enough WIPE-OUT™ in a can to clean more than 100 firearms .It is recommended for rifles, pistols, revolvers, shotguns, and it works with all muzzle loading firearms . WIPE-OUT™ will also clean flash-hiders , muzzle brakes, and silencers .The suggested retail price is \$13.99 per can .It's made in the United States and meets all governmental criteria .



Sharp Shoot R Precision Inc Box 171 -Paola , KS 66071
785-883-4444 Pho . -785-883-2525 Fax

web site: [web site =www.sharpshootr.com](http://www.sharpshootr.com) email: [getinfo @ sharpshootr.com](mailto:getinfo@sharpshootr.com)



Try New ACCELERATOR™ for Wipe-Out™ it will double the speed of Wipe-Out™ and double the amount of fouling removed, especially copper and carbon. An 8 ounce bottle of ACCELERATOR™ retails for \$9.99 per bottle and will last through about 3 cans of Wipe-Out™. To apply, simply wet a patch with ACCELERATOR™ and shoot Wipe-Out™ in right behind it